# Richmond Refinery LPS Alert - Reliability H2 Recycle Compressor Trip - 9/26/2010





IPS Control: 2036930

Location: Richmond

### **Contact Information:**

Tony Vink 242-2843 VINK@chevron.com



**Power Supply** 



3/4 amp slow blow fuse incorrectly inserted here

Always remember to do your LPSA – because we care about you!

# **Incident Description:**

4 Rheniformer H2 Recycle Compressor (K-3550) tripped off line. Operations responded and found the Trisen speed controller had no power on the panel.

## **Immediate Actions Taken:**

Operators made notifications, chopped furnaces, pulled feed, and depressurized the reactor loop without causing any environmental issues. The DHT slumped due to loss of hydrogen and it was routed off test. In addition, 5 cat feed was increased to partially mitigate the loss of 4 cat.

Process control was called and consulted. Electrician and instrument personnel were called out to troubleshoot. They found that a 3/4 Amp fuse had blown on the Trisen inlet power, which should have been a 5 Amp fuse. The fuse was replaced with the proper 5 Amp fuse and Operations started preparing the plant for restart.

K-3550 was brought back up to a slow roll two hours after it had tripped. Feed was re-introduced to the plant seven hours after the compressor tripped.

An investigation into the source and cause of the incorrectly sized fuse is underway.

# **Background Information**

There are 2 power supplies that are used for Trisen TS-310 speed controllers. The first one uses an AC power source that requires a ¾ amp slow blow fuse. The second one is a special battery backup power supply, 24 Vdc, that requires a 5 amp slow blow fuse (this kind of power supply was the one in service, except that it had a 3/4 Amp fuse in it). The Trisen inlet power module is purchased prefabricated by the manufacturer.

#### Immediate Recommendations

Compressors with Trisen power supplies in service may be at risk for a similar type of failure. All sites should determine if any of their compressors are at risk and check the fuses in the Trisen power supplies for those compressors. Contingency plans for a similar type of failure should be developed if the compressor power supply fuse can not be checked without affecting plant rates.



This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.